Declassification Review by NGA/DoD

OUT54943

1965 JAN 28 23 04 Z

25X1

Act. R

R.S. WALL BU

COPIES RECEIVED

Office

SEC BR

P&DS CSD

IPD PD

PSD TID

PAG CIA/PID DIA 1 (-4

Destroyed

Master File

- S E C R E T 282246Z
- 1. CAMERA B-101 WAS USED IN MISSION 3986 FLOWN ON 27 JANUARY 1965; PROCESSING WAS ACCOMPLISHED BY BARKSDALE AFB.
 - 2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS FAIR TO

GOOD.

B. 9R SIDE: ROLLER "CHATTER" IS PRESENT ALONG BOTH SIDES OF THE FILM AT THE BEGINNING OF THE MISSION. THE "CHATTER" TAKES THE FORM OF ELLIPTICAL SPOTS ON THE INBOARD SIDE. MARKING INK TRANSFERSFROM THE LEADER APPEAR ON THE BASE OF FRAMES 600, 1200 AND 1500.

PART FOUR WAS SPOOLED BASE OUT. CHEMICAL AND/OR WATER SPOTS ARE FOUND ON FRAMES 1672 TO 1673. A MANUFACTURER'S SPLICE AND ASSOCIATED STATIC IS LOCATED IN FRAME 1719.

C. 9L SIDE: EDGE FOG IS PRESENT ON THE INBOARD EDGE THROUGHOUT THE MISSION. EDGE FOG OCCURS INTERMITTENTLY ON THE OUTBOARD
EDGE. A MANUFACTURING SPLICE AND ASSOCIATED STATIC IS LOCATED ON

FRAME 647.

- D. BOTH SIDES: EDGE STATIC IS PRESENT ALONG BOTH EDGES INTERMITTENTLY THROUGHOUT THE MISSION. THE LAST TITLED FRAME IS 1999.
- E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS IN THIS MISSION.
 - 3. POSITIVE:





- A. THE PI SUITABILITY IS FROM FAIR TO GOOD.
- B. THE PRINTING AND PROCESSING WAS GOOD.
- C. CLOUDS DEGRADED OR OBSCURED 10 PERCENT OF THE MISSION.

- 124

SECRET

/END OF MESSAGE/